

CITY OF ANCHORAGE - 2021 HAZARD TREE INVENTORY

	ADDRESS/LOCATION	TYPE OF TREE	SIZE	HAZARD/PRUNE	COMMENTS
1	12203 SURREY LANE (ON CURVE)	SYCAMORE	17"	HAZARD	
2	805 SURREY LANE	OAK	32"	HAZARD	
3	OWL CREEK LANE (ACROSS FROM 1203 OLD HARRODS CREEK RD.- OWL CREEK SIDE)	WALNUT	38"	HAZARD	
4	1401 WALNUT LANE	DOGWOOD	MULTI-TRUNKED	HAZARD	DEAD
5	11708 LITTLE LANE	BOXELDER	12"	HAZARD	ON SOUTH SIDE OF THE STREET ACROSS FROM THIS ADDRESS
6	1102 OLD HARRODS CREEK ROAD	WALNUT	25"	HAZARD	
7	1102 OLD HARRODS CREEK ROAD	HONEYLOCUST	32.5"	HAZARD	
8	1200 OLD HARRODS CREEK ROAD	ASH	27"	HAZARD	
9	MEDIAN AT END OF SOMERHILL WAY	SPRUCE	15.75"	HAZARD	
10	MEDIAN AT END OF SOMERHILL PLACE	SPRUCE	10.5"	HAZARD	
11	GLENBROOK ROAD TRIANGLE (NEAR EAST OSAGE ROAD INTERSECTION)	STUMP		STUMP REMOVAL	
12	GLENBROOK ROAD TRIANGLE (NEAR EAST OSAGE ROAD INTERSECTION)	STUMP		STUMP REMOVAL	THIS IS NOT A DUPLICATE-THERE ARE TWO STUMPS IN THE TRIANGLE TO BE REMOVED
13	City Hall (next to RR Tracks from Evergreen Road to Park Road)	STUMPS (8)		8 STUMP REMOVALS	TOTAL OF 8 STUMPS ALONG RR TRACKS
14	EAST OSAGE ROAD ACROSS FROM COLD SPRINGS TRIANGLE AT EAST OSAGE RD	WALNUT	21"	PRUNE	PRUNE LOW-HANGING BRANCHES OVER THE STREET
15	EAST OSAGE ROAD ACROSS FROM COLD SPRINGS TRIANGLE AT EAST OSAGE RD	WALNUT	25"	PRUNE	PRUNE LOW-HANGING BRANCHES OVER THE STREET
16	12202 MISTLETOE ROAD	MAPLE	25"	PRUNE	PRUNE LOW HANGING BRANCHES OVER THE STREET AT THE CORNER OF MISTLETOE ROAD & NORTH OSAGE ROAD
17	12306 MISTLETOE ROAD	SYCAMORE	30"	PRUNE	LIMB UP SYCAMORE WITH LOW HANGING BRANCHES OVER THE STREET AT THE INTERSECTION OF HOLLY LN & MISTLETOE RD
18	12309 HOLLY LANE	REDBUD	12"	PRUNE	PRUNE 9" SPLIT LIMB ON THIS TREE WHICH OVERHANGS FRONT OF DRIVEWAY AT 12311 HOLLY LN & THE STREET
19	2501 LITTLE HILLS LANE	ASH	30"	HAZARD	NEAR DRIVEWAY
20	2503 LITTLE HILLS LANE	DEAD	10"	HAZARD	THIS TREE IS LEANING TOWARDS THE STREET
21	2700 ANCHOR WAY	DEAD	6"	HAZARD	ACROSS FROM THE DRIVEWAY OF 2701 ANCHOR WAY
22	2700 ANCHOR WAY	CHERRY	MULTI-TRUNKED	HAZARD	ACROSS FROM THE DRIVEWAY OF 2701 ANCHOR WAY
23	2700 ANCHOR WAY	BLACK GUM	MULTI-TRUNKED	HAZARD	LEFT OF DRIVEWAY
24	2701 ANCHOR WAY	MULBERRY	MULTI-TRUNKED	HAZARD	
25	2701 ANCHOR WAY	SPRUCE	MULTI-TRUNKED	HAZARD	NEAR THE INTERSECTION OF CREST ARM
26	2403 ANCHOR WAY	DEAD	8"	HAZARD	ACROSS FROM THE MAILBOX AT 12700 OLD LAGRANGE ROAD (LUCAS LANE SIDE)
27	Ridge Road between Evergreen Road and Bellewood Road (by RR Tracks)	NORWAY SPRUCE	8"	HAZARD	BETWEEN EDGE OF RIDGE ROAD AND RAILROAD TRACKS
28	Ridge Road between Evergreen Road and Bellewood Road (by RR Tracks)	ASH	10"	HAZARD	BETWEEN EDGE OF RIDGE ROAD AND RAILROAD TRACKS
29	Ridge Road between Evergreen Road and Bellewood Road (by RR Tracks)	MAPLE	12.5"	HAZARD	BETWEEN EDGE OF RIDGE ROAD AND RAILROAD TRACKS

DISCLAIMER: We, as horticultural consultants, are tree specialists who use our education, knowledge, training and experience within the fields of horticulture, arboriculture, and urban forestry to examine trees, recommend measures to enhance their health and beauty, and to attempt to reduce the risk of living near trees. Trees, as well as other plants, are living, changing organisms affected by innumerable factors beyond our control. Trees fail in ways, and because of, conditions we do not fully understand. Hanlon Horticultural Consultants cannot detect or anticipate every condition or event that could possibly lead to the structural failure of a tree. Conditions affecting the health and safety of a tree are often hidden within in the tree itself and are below ground as well. We cannot guarantee that a tree will be healthy or safe under all circumstances for any specific period, or when a tree or its parts may fail. Trees can be managed, but not controlled. To live near trees, regardless of their condition, is to accept some degree of risk. The only way to eliminate all risk associated with trees is to eliminate all trees.