

CITY OF ANCHORAGE
HAZARDOUS TREE INVENTORY
DUE DATE 8 JANUARY 2021
12:00 P.M. Anchorage City Hall

Questions: please call Anchorage Public Works
502.245.9700

ADDRESS/LOCATION	TREE NUMBER (P=PRUNE ONLY)	TYPE OF TREE	SIZE	HAZARD(REMOVE)/PRUNE	COMMENTS
11907 LOG CABIN LANE	1P	MAPLE		PRUNE	PRUNE DEAD AND/OR BROKEN HANGING BRANCHES OVER THE STREET
12004 LOG CABIN LANE	2	MAPLE	DOUBLE-TRUNKED	HAZARD	LEFT OF DRIVEWAY OFF SHADY LANE.
12207 LOG CABIN LANE	3	OAK	40+"	HAZARD	
12300 LOG CABIN/SURREY LANE	4	HACKBERRY	12"	HAZARD	NEAR THE BEND OF THE STREET
12300 LOG CABIN/SURREY LANE	5	HACKBERRY	9"	HAZARD	NEAR THE BEND OF THE STREET
12300 LOG CABIN/SURREY LANE	6	ASH	12"	HAZARD	NEAR THE BEND OF THE STREET
12101 LOG CABIN LANE	7	BLACK WALNUT	21"	HAZARD	CORNER OF SHADY LANE
11801 WOODLAND ROAD	8	OAK	40+"	HAZARD	EVERGREEN ROAD SIDE NEXT TO SIDEWALK
12001 WOODLAND ROAD	9	MAPLE	32"	HAZARD	LG&E will remove top of tree to make it safe to remove the tree below the utility lines. (1/4/21)
702 SHADY LANE	10	HACKBERRY	12"	HAZARD	
1307 GLENBROOK ROAD	11	MAPLE	DOUBLE-TRUNKED	HAZARD	
12106 LOCUST LANE	12P	OAK	40+"	PRUNE	TREE LOCATED TO RIGHT OF DRIVEWAY OF THIS ADDRESS. PRUNE DEAD LOWER BRANCHES HANGING OVER THE STREET.
11906 RIDGE ROAD	13	MAPLE	20.5"	HAZARD	AT SHADY LANE INTERSECTION
11102 OWL CREEK LANE	14	OAK	42"	HAZARD	LOCATED TO THE RIGHT OF THE DRIVEWAY HERE
11108 BEECH ROAD	15	HACKBERRY	16"	HAZARD	
11108 BEECH ROAD	16	HACKBERRY	27"	HAZARD	
1102 BELLEWOOD ROAD	17	ASH	48+"	HAZARD	RIGHT SIDE OF DRIVEWAY
1102 BELLEWOOD ROAD	18	DEAD	32"	HAZARD	
12902 NORTH OSAGE ROAD	19P	OAK	42"	PRUNE	PRUNE DEAD LOWER BRANCHES
12805 NORTH OSAGE ROAD	20P	OAK	55+"	PRUNE	LOCATED NEAR THE PASTURES. PRUNE BROKEN HANGING BRANCH OVER FENCE.
12407 LUCAS LANE	21	CEDAR	13"	HAZARD	DEAD
12504 LUCAS LANE	22	ASH	29"	HAZARD	
2403 CAVE SPRINGS PLACE	23	BLACK LOCUST	MULTI-TRUNKED	HAZARD	
2403 CAVE SPRINGS PLACE	24	BOXELDER	MULTI-TRUNKED	HAZARD	
2405 ANCHOR WAY	25	MAPLE	DOUBLE-TRUNKED	HAZARD	
2405 ANCHOR WAY	26	MAPLE	8"	HAZARD	
2405 ANCHOR WAY	27	DEAD	7"	HAZARD	ACROSS FROM 2701 ANCHOR WAY DRIVEWAY
2405 ANCHOR WAY	28	DEAD	3"	HAZARD	ACROSS FROM 2701 ANCHOR WAY DRIVEWAY
2501 LITTLE HILLS LANE	29P	OAK	38"	PRUNE	OPPOSITE THE FIRST DRIVEWAY OF THIS ADDRESS. PRUNE BROKEN HANGING BRANCHES OVER THE STREET.
2506 NUTWOOD DRIVE	30	MAPLE	27"	HAZARD	
1503 EVERGREEN ROAD	31P	GINKGO	28.5"	PRUNE	PRUNE DEAD BRANCHES OVER THE SIDEWALK, EAST OSAGE ROAD SIDE
WAGNER PARK	32	SUGAR MAPLE	32"	HAZARD	NEAR THE BACK OF THE WINKLERS' HOME
WAGNER PARK	33 (Delete from Inventory)	DOGWOOD	3"	HAZARD	(This tree has already been removed. Exclude this from this list.)
WAGNER PARK	34	SPRUCE	14"	HAZARD	LEFT (WEST) END OF PARK
		SUMMARY:	6 TREES	PRUNE	
			27 TREES	REMOVE	
		Bid to include stump removal and debris haul away			

DISCLAIMER: We, as horticultural consultants, are tree specialists who use our education, knowledge, training and experience within the fields of horticulture, arboriculture, and urban forestry to examine trees, recommend measures to enhance their health and beauty, and to attempt to reduce the risk of living near trees. Trees, as well as other plants, are living, changing organisms affected by innumerable factors beyond our control. Trees fail in ways, and because of, conditions we do not fully understand. Hanlon Horticultural Consultants cannot detect or anticipate every condition or event that could possibly lead to the structural failure of a tree. Conditions affecting the health and safety of a tree are often hidden within in the tree itself and are below ground as well. We cannot guarantee that a tree will be healthy or safe under all circumstances for any specific period, or when a tree or its parts may fail. Trees can be managed, but not controlled. To live near trees, regardless of their condition, is to accept some degree of risk. The only way to eliminate all risk associated with trees is to eliminate all trees.